



## Perfect Retrofits, Burlington, ON

A trio of buildings developed a problem with another brand of IG Unit. They were breaking down and not delivering the increased R-Values promised. ECO Insulating Glass is tasked with replacing the failed IG Units over a scheduled period of time.

The challenge is to match the architectural look so it doesn't look like a patchwork quilt. With an outboard lite of 6mm Viracon VS1-14 and an inboard lite of clear 6mm, we chose a single film of ECOGLASS/HM 88 suspended in the original overall width of 2 7/8" from the replaced units. A silver spacer is used. The new ECO IG Units are filled with krypton gas to achieve an R-Value of 6 – three times the insulating value of traditional dual pane IG Units.

Equally important, the new ECOGLASS/HM units are a perfect match. Take a look.

## 1100 Burloak Drive



5420 North Service Road



5515 North Service Road

